

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>L</b>					
694	La Toulousaine	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
695	Lakal	40 Mhz	FSK	T102497-40-5	
696		40 Mhz	FSK	T397-40-2	
697	Lawiczak	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
698	Layh	40 Mhz	FSK	RFKCO-40-5	
699		40 Mhz	FSK	T102497-40-5	
700		40 Mhz	FSK	T397-40-2	
701		40 Mhz	FSK	TX02-40-2	
702		40 Mhz	FSK	TX03-40-1/5	
703		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
704	LEEB	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
705	LEPINARD	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
706	Lift-Master	27 Mhz	FSK	1A3531	
707		27 Mhz	FSK	750E	
708		27 Mhz	FSK	G3156	
709		27 Mhz	FSK	G3271E(1B)	
710		27 Mhz	FSK	G3272E	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>L</b>					
711	Lift-Master	27 Mhz	FSK	G750EML	
712		27 Mhz	FSK	G751EML	
713		27 Mhz	FSK	G752EML(2B)	
714		27 Mhz	FSK	G754EML(4B)	
715		40 Mhz	FSK	1A3570	
716		418 Mhz	ASK	G 4180 EML	
717		418 Mhz	ASK	G 4183 E	
718		418 Mhz	ASK	G 4185 E	
719		433 Mhz	ASK	94335E	
720		433 Mhz	ASK	G 4330 E	
721		433 Mhz	ASK	G 4332 E (2B)	
722		433 Mhz	ASK	G 4333 E (3B)	
723		433 Mhz	ASK	G 4335 E	
724		868 Mhz	ASK	98685E	ab/up/depuis/dal/desde Software Version 7
725	Lindpointner Torbau	40 Mhz	FSK	RFKCO-40-5	
726		40 Mhz	FSK	T102497-40-5	
727		40 Mhz	FSK	T397-40-2	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>L</b>					
728	Lindpointner Torbau	40 Mhz	FSK	TX02-40-2	
729		40 Mhz	FSK	TX03-40-1/5	
730		40 Mhz	FSK	TX04-40-15	
731		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7