

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|--------------|-----------|------|------------------|--|
| S | | | | | |
| 977 | Scarpatoni | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 978 | Schalk | 433 Mhz | ASK | FSH-4 | |
| 979 | | 433 Mhz | ASK | FSH-8 | |
| 980 | Scharpf | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 981 | Schellenberg | 433 Mhz | ASK | Mizar / 21250 | |
| 982 | Schmoelling | 40 Mhz | FSK | T102497-40-5 | |
| 983 | | 40 Mhz | FSK | T397-40-2 | |
| 984 | | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 985 | Schneider | 40 Mhz | FSK | RFKCO-40-5 | |
| 986 | | 40 Mhz | FSK | T102497-40-5 | |
| 987 | | 40 Mhz | FSK | T397-40-2 | |
| 988 | | 40 Mhz | FSK | TX02-40-2 | |
| 989 | | 40 Mhz | FSK | TX03-40-1/5 | |
| 990 | | 40 Mhz | FSK | TX04-40-15 | |
| 991 | | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 992 | Schuetz | 40 Mhz | FSK | RFKCO-40-5 | |
| 993 | | 40 Mhz | FSK | T102497-40-5 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|-----------|-----------|------|------------------------|--|
| S | | | | | |
| 994 | Schuetz | 40 Mhz | FSK | T397-40-2 | |
| 995 | | 40 Mhz | FSK | TX02-40-2 | |
| 996 | | 40 Mhz | FSK | TX04-40-15 | |
| 997 | | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 998 | Schwaben | 40 Mhz | ASK | - | |
| 999 | Schweiger | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1000 | SCOPE | 418 Mhz | ASK | - | |
| 1001 | seav | 30 Mhz | ASK | - | |
| 1002 | | 433 Mhz | AM | BeEasy TX | |
| 1003 | | 433 Mhz | AM | BeEasy TX Rolling Code | ab/up/depuis/dal/desde Software Version 7 |
| 1004 | | 433 Mhz | AM | BeHappy RH1 | ab/up/depuis/dal/desde Software Version 7 |
| 1005 | | 433 Mhz | AM | BeHappy RH2 | ab/up/depuis/dal/desde Software Version 7 |
| 1006 | | 433 Mhz | AM | BeHappy RH3 | ab/up/depuis/dal/desde Software Version 7 |
| 1007 | | 433 Mhz | AM | BeHappy RS1 | ab/up/depuis/dal/desde Software Version 7 |
| 1008 | | 433 Mhz | AM | BeHappy RS2 | ab/up/depuis/dal/desde Software Version 7 |
| 1009 | | 433 Mhz | AM | BeHappy RS3 | ab/up/depuis/dal/desde Software Version 7 |
| 1010 | | 433 Mhz | AM | BeHappy S1 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|------------|-----------|------|------------------|--|
| S | | | | | |
| 1011 | seav | 433 Mhz | AM | BeHappy S2 | |
| 1012 | | 433 Mhz | AM | BeHappy S3 | |
| 1013 | | 433 Mhz | AM | TRS 1 | ab/up/depuis/dal/desde Software Version 7 |
| 1014 | | 433 Mhz | AM | TRS 2 | ab/up/depuis/dal/desde Software Version 7 |
| 1015 | | 433 Mhz | AM | TXS 1 | |
| 1016 | | 433 Mhz | AM | TXS 2 | |
| 1017 | | 433 Mhz | AM | TXS 3 | |
| 1018 | | 433 Mhz | AM | TXS 4 | |
| 1019 | | 433 Mhz | AM | TXS ESA | |
| 1020 | | 433 Mhz | ASK | TXS ESA | |
| 1021 | | 433 Mhz | ASK | TXS1 | |
| 1022 | | 433 Mhz | ASK | TXS2 | |
| 1023 | | 433 Mhz | ASK | TXS3 | |
| 1024 | Sectic-Tec | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1025 | Seculux | 40 Mhz | FSK | RFKCO-40-5 | |
| 1026 | | 40 Mhz | FSK | T102497-40-5 | |
| 1027 | | 40 Mhz | FSK | T397-40-2 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|---------|-----------|------|------------------|-------|
| S | | | | | |
| 1028 | Seculux | 40 Mhz | FSK | TX02-40-2 | |
| 1029 | | 40 Mhz | FSK | TX03-40-1/5 | |
| 1030 | | 40 Mhz | FSK | TX04-40-15 | |
| 1031 | Seip | 27 Mhz | ASK | - | |
| 1032 | | 27 Mhz | ASK | - | |
| 1033 | | 27 Mhz | ASK | 27 AM | |
| 1034 | | 40 Mhz | AM | - | |
| 1035 | | 40 Mhz | ASK | 40 AM | |
| 1036 | | 40 Mhz | FSK | - | |
| 1037 | | 40 Mhz | FSK | 40 FM | |
| 1038 | | 433 Mhz | ASK | - | |
| 1039 | | 433 Mhz | ASK | 433-12 AM | |
| 1040 | | 433 Mhz | ASK | SKR 433 | |
| 1041 | | 433 Mhz | ASK | SKRJ433 | |
| 1042 | Selve | 40 Mhz | FSK | 297112 | |
| 1043 | | 40 Mhz | FSK | 297113 | |
| 1044 | | 40 Mhz | FSK | 297114 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|----------|-----------|------|------------------|--|
| S | | | | | |
| 1045 | Selve | 40 Mhz | FSK | 297121 Mini | |
| 1046 | | 433 Mhz | ASK | 297141 | |
| 1047 | | 433 Mhz | ASK | 297142 | |
| 1048 | | 433 Mhz | ASK | 297143 | |
| 1049 | | 433 Mhz | ASK | 297145 Mini | |
| 1050 | | 433 Mhz | ASK | 297344 | |
| 1051 | Serai | 433 Mhz | AM | OG/52 | |
| 1052 | | 433 Mhz | AM | OG/54 | |
| 1053 | Sich Tel | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1054 | Siebau | 433 Mhz | ASK | MAX43-2 | |
| 1055 | | 433 Mhz | ASK | MAX43-4 | |
| 1056 | | 433 Mhz | ASK | MC43-2 | |
| 1057 | | 433 Mhz | ASK | MCHS43-2 | |
| 1058 | | 433 Mhz | ASK | MHS43-2 | |
| 1059 | | 433 Mhz | ASK | MHS43-4 | |
| 1060 | | 433 Mhz | ASK | MIX43-2 | |
| 1061 | | 433 Mhz | ASK | MS43-2 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|----------|--------------------------------|-----------|------|------------------|--|
| S | | | | | |
| 1062 | Siebau | 433 Mhz | ASK | MS43-4 | |
| 1063 | | 433 Mhz | ASK | Multibit | |
| 1064 | Silento | 433 Mhz | ASK | Digital 211 | |
| 1065 | | 433 Mhz | ASK | Digital 212 | |
| 1066 | | 433 Mhz | ASK | Digital 214 | |
| 1067 | | 433 Mhz | ASK | Digital 221 | |
| 1068 | | 433 Mhz | ASK | Digital 222 | |
| 1069 | | 433 Mhz | ASK | Digital 224 | |
| 1070 | | 433 Mhz | ASK | Digital 231 | |
| 1071 | Sistema | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1072 | smd | 27 Mhz | ASK | LW27HS98 | |
| 1073 | | 27 Mhz | ASK | LW27/40BS4N | |
| 1074 | | 27 Mhz | ASK | LW40 MS3/4 | |
| 1075 | | 40 Mhz | ASK | - | |
| 1076 | | 40 Mhz | ASK | 40HS98K/U | |
| | Red buttons are not compatible | | | | |
| 1077 | | 40 Mhz | ASK | 40MIU/IK | |
| | Red buttons are not compatible | | | | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|------|--------------------------------|-----------|------|------------------|-------|
| 1078 | | 40 Mhz | ASK | 40MS3/4 | |
| | Red buttons are not compatible | | | | |
| 1079 | | 40 Mhz | ASK | LW40BSS4 | |
| 1080 | | 40 Mhz | ASK | MS4099U/K | |
| | Red buttons are not compatible | | | | |
| 1081 | | 433 Mhz | ASK | LW433MIAU | |
| 1082 | | 433 Mhz | FSK | - | |
| 1083 | | 433 Mhz | FSK | LW433HS98FU/FK | |
| 1084 | | 433 Mhz | FSK | LW433MS2 | |
| 1085 | Sommer | 27 Mhz | ASK | S-435-B | |
| 1086 | | 27 Mhz | FSK | T102497-27-5 | |
| 1087 | | 40 Mhz | ASK | S-435-40 | |
| 1088 | | 40 Mhz | FSK | RFKCO-40-5 | |
| 1089 | | 40 Mhz | FSK | T102497-40-5 | |
| 1090 | | 40 Mhz | FSK | T397-40-2 | |
| 1091 | | 40 Mhz | FSK | TX02-40-2 | |
| 1092 | | 40 Mhz | FSK | TX03-40-1/5 | |
| 1093 | | 40 Mhz | FSK | TX04-40-15 | |
| 1094 | | 433 Mhz | FSK | TX02-434-2 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|------|-------------|-----------|------|------------------|--|
| 1095 | | 433 Mhz | FSK | TX03-434-4 | |
| 1096 | | 433 Mhz | FSK | TX03-434-4XP | |
| 1097 | | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1098 | | 868 Mhz | FSK | TX03-868-4-XP | ab/up/depuis/dal/desde Software Version 7 |
| 1099 | | 868 Mhz | FSK | TX03-8-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1100 | Sonico | 40 Mhz | FSK | T102497-40-5 | |
| 1101 | | 40 Mhz | FSK | T397-40-2 | |
| 1102 | Sonnleitner | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1103 | SPPF | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1104 | STA | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1105 | Stadelbauer | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1106 | Standoor | 433 Mhz | ASK | G 4330 E | |
| 1107 | | 433 Mhz | ASK | G 4332 E | |
| 1108 | | 433 Mhz | ASK | G 4333 E | |
| 1109 | | 433 Mhz | ASK | G 4335 E | |
| 1110 | Stanley | 40 Mhz | ASK | 1083-12 | |
| 1111 | Steelline | 868 Mhz | ASK | 868-4C | ab/up/depuis/dal/desde Software Version 7 |
| 1112 | Stock | 40 Mhz | FSK | T102497-40-5 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|------|---------|-----------|------|------------------|--|
| 1113 | | 40 Mhz | FSK | T397-40-2 | |
| 1114 | | 868 Mhz | FSK | TX03-868-4 | ab/up/depuis/dal/desde Software Version 7 |
| 1115 | SUPEERO | 27 Mhz | ASK | SM1 | |
| 1116 | | 27 Mhz | ASK | SM1DL | |
| 1117 | | 27 Mhz | ASK | SM1MD | |
| 1118 | | 27 Mhz | ASK | SM2 | |
| 1119 | | 27 Mhz | ASK | SM2DL | |
| 1120 | | 27 Mhz | ASK | SM2MD | |
| 1121 | | 27 Mhz | ASK | SM3 | |
| 1122 | | 27 Mhz | ASK | SM3DL | |
| 1123 | | 27 Mhz | ASK | SM3MD | |
| 1124 | | 27 Mhz | ASK | SM4 | |
| 1125 | | 27 Mhz | ASK | SM4DL | |
| 1126 | | 27 Mhz | ASK | SM4MD | |
| 1127 | | 40 Mhz | ASK | SKLC1 | |
| 1128 | | 40 Mhz | ASK | SKLC2 | |
| 1129 | | 40 Mhz | ASK | SKLC3 | |
| 1130 | | 40 Mhz | ASK | SKLC4 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|------|---------|-----------|------|------------------|-------|
| 1131 | | 433 Mhz | ASK | SKX1 | |
| 1132 | | 433 Mhz | ASK | SKX1DL | |
| 1133 | | 433 Mhz | ASK | SKX1MD | |
| 1134 | | 433 Mhz | ASK | SKX2 | |
| 1135 | | 433 Mhz | ASK | SKX22 | |
| 1136 | | 433 Mhz | ASK | SKX2DL | |
| 1137 | | 433 Mhz | ASK | SKX2MD | |
| 1138 | | 433 Mhz | ASK | SKX3 | |
| 1139 | | 433 Mhz | ASK | SKX33 | |
| 1140 | | 433 Mhz | ASK | SKX33DL | |
| 1141 | | 433 Mhz | ASK | SKX3DL | |
| 1142 | | 433 Mhz | ASK | SKX3MD | |
| 1143 | | 433 Mhz | ASK | SKX4 | |
| 1144 | | 433 Mhz | ASK | SKX44 | |
| 1145 | | 433 Mhz | ASK | SKX44DL | |
| 1146 | | 433 Mhz | ASK | SKX4DL | |
| 1147 | | 433 Mhz | ASK | SKX4MD | |
| 1148 | | 433 Mhz | ASK | SKX88 | |

06.07.2010

Hotline (0) 08000 466 354 65

COMPATIBILITY LIST

Please note: Currently, software version 7 is installed in the following vehicles:

| | |
|-----------------------|--|
| Alfa Romeo: | Alfa 159, Alfa 159 Sportwagon |
| Aston Martin: | DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster |
| Audi: | Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009) |
| BMW: | from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6 |
| Jaguar: | XF |
| Land Rover: | Range Rover |
| Lexus: | IS, GS, RX, LS |
| Maserati: | Coupé, Granturismo, Quattroporte |
| Mercedes-Benz: | from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class |
| MINI: | MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper |
| Porsche: | 911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne |
| Toyota: | Auris, Corolla, Avensis, RAV4, Land Cruiser |
| Volkswagen: | Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg |
| Volvo: | XC90, S80, C70, V70, XC60, V50, S40, C30 |

| UK | Company | Frequency | Mod. | Transmitter Type | Notes |
|------|---------|-----------|------|------------------|-------|
| 1149 | | 433 Mhz | ASK | SKX88DL | |
| 1150 | | 433 Mhz | ASK | SSKX4DL | |
| 1151 | | 433 Mhz | ASK | SSKX4MD | |