

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
549	Hacker	27 Mhz	ASK	27AM	
550		40 Mhz	ASK	40AM	
551		40 Mhz	FSK	40FM	
552		433 Mhz	ASK	SKR 433	
553		433 Mhz	ASK	SKRJ 433	
554	Hees + Peters	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
555	Heinzmann	868 Mhz	FSK	657100	ab/up/depuis/dal/desde Software Version 7
556		868 Mhz	FSK	657110	ab/up/depuis/dal/desde Software Version 7
557		868 Mhz	FSK	657132	ab/up/depuis/dal/desde Software Version 7
558		868 Mhz	ASK	656600	ab/up/depuis/dal/desde Software Version 7
559		868 Mhz	ASK	656632	ab/up/depuis/dal/desde Software Version 7
560	Henderson	27 Mhz	FSK	T102497-27-5	
561		40 Mhz	FSK	RFKCO-40-5	
562		40 Mhz	FSK	T102497-27-5	
563		40 Mhz	FSK	T102497-40-5	
564		40 Mhz	FSK	T397-40-2	
565		40 Mhz	FSK	TX02-40-2	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
566	Henderson	40 Mhz	FSK	TX03-40-1/5	
567		40 Mhz	FSK	TX04-40-15	
568		433 Mhz	ASK	4K AM HS	
569		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
570	Heroal	40 Mhz	FSK	RFKCO-40-5	
571		40 Mhz	FSK	T102497-40-5	
572		40 Mhz	FSK	T397-40-2	
573		40 Mhz	FSK	TX02-40-2	
574		40 Mhz	FSK	TX03-40-1/5	
575		40 Mhz	FSK	TX04-40-15	
576		433 Mhz	ASK	Pocket-1K	
577		433 Mhz	ASK	Pocket-2K	
578		433 Mhz	ASK	Pocket-4K	
579		433 Mhz	ASK	S3-4	
580		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
581	Hild-Tortechnik	40 Mhz	FSK	T102497-40-5	
582		40 Mhz	FSK	T397-40-2	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
583	Hild-Tortechnik	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
584	HL Torbau	40 Mhz	FSK	RFKCO-40-5	
585		40 Mhz	FSK	T102497-40-5	
586		40 Mhz	FSK	T397-40-2	
587		40 Mhz	FSK	TX02-40-2	
588		40 Mhz	FSK	TX03-40-1/5	
589		40 Mhz	FSK	TX04-40-15	
590	Hochtief	40 Mhz	FSK	T102497-40-5	
591		40 Mhz	FSK	T397-40-2	
592	Hoermann <small>Valid for transmitters with green buttons</small>	27 Mhz	ASK	DH 01	
593	<small>Valid for transmitters with green buttons</small>	27 Mhz	ASK	DH 02	
594	<small>Valid for transmitters with green buttons</small>	27 Mhz	ASK	DH 03	
595	<small>Valid for transmitters with green buttons</small>	27 Mhz	ASK	DH 04	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
596	Hoermann	40 Mhz	ASK	EcoStar 2	
597		40 Mhz	ASK	EcoStar 4	
598		40 Mhz	ASK	FCT10b-40	
599		40 Mhz	ASK	HS16-40	
600		40 Mhz	ASK	HS2-40	
	Valid for transmitters with grey buttons				
601		40 Mhz	ASK	HS4-40	
	Valid for transmitters with grey buttons				
602		40 Mhz	ASK	HSE2-40	
	Valid for transmitters with grey buttons				
603		40 Mhz	ASK	HSM2-40	
	Valid for transmitters with grey buttons				
604		40 Mhz	ASK	HSM4-40	
	Valid for transmitters with grey buttons				
605		433 Mhz	ASK	RCT3b-433	
606		433 Mhz	ASK	RS2-433	
	Valid for transmitters with yellow buttons				

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
607	Hoermann <small>Valid for transmitters with yellow buttons</small>	433 Mhz	ASK	RS4-433	
608		433 Mhz	ASK	RSE2-433	
609	<small>Valid for transmitters with yellow buttons</small>	433 Mhz	ASK	RSM2-433	
610	<small>Valid for transmitters with yellow buttons</small>	433 Mhz	ASK	RSM4-433	
611		868 Mhz	ASK	FCT10b-868	ab/up/depuis/dal/desde Software Version 7
612		868 Mhz	ASK	FCT3b-868	ab/up/depuis/dal/desde Software Version 7
613	<small>Valid for transmitters with blue buttons</small>	868 Mhz	ASK	HS1-868	ab/up/depuis/dal/desde Software Version 7
614		868 Mhz	ASK	HS16-868	ab/up/depuis/dal/desde Software Version 7
615	<small>Valid for transmitters with blue buttons</small>	868 Mhz	ASK	HS2-868	ab/up/depuis/dal/desde Software Version 7
616	<small>Valid for transmitters with blue buttons</small>	868 Mhz	ASK	HS4-868	ab/up/depuis/dal/desde Software Version 7
617		868 Mhz	ASK	HSD2-868	ab/up/depuis/dal/desde Software Version 7

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
618	Hoermann Valid for transmitters with blue buttons	868 Mhz	ASK	HSE2-868	ab/up/depuis/dal/desde Software Version 7
619		868 Mhz	ASK	HSI-868	ab/up/depuis/dal/desde Software Version 7
620	Valid for transmitters with blue buttons	868 Mhz	ASK	HSM2-868	ab/up/depuis/dal/desde Software Version 7
621	Valid for transmitters with blue buttons	868 Mhz	ASK	HSM4-868	ab/up/depuis/dal/desde Software Version 7
622	Valid for transmitters with blue button	868 Mhz	ASK	HSP4-868	ab/up/depuis/dal/desde Software Version 7
623		868 Mhz	ASK	HSZ1-868	ab/up/depuis/dal/desde Software Version 7
624		868 Mhz	ASK	HSZ2-868	ab/up/depuis/dal/desde Software Version 7
625	Hofbauer	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
626	Holder	40 Mhz	FSK	RFKCO-40-5	
627		40 Mhz	FSK	T102497-40-5	
628		40 Mhz	FSK	T397-40-2	
629		40 Mhz	FSK	TX02-40-2	
630		40 Mhz	FSK	TX03-40-1/5	

06.07.2010

Hotline (0) 08000 466 354 65

## COMPATIBILITY LIST

**Please note: Currently, software version 7 is installed in the following vehicles:**

<b>Alfa Romeo:</b>	Alfa 159, Alfa 159 Sportwagon
<b>Aston Martin:</b>	DB9 Coupé, DB9 Volante, V8 Vantage, V8 Roadster
<b>Audi:</b>	Audi A8 (model year 2008), Audi A6 (model year 2009), Audi A5, Audi A4 (B8), Audi A3 Cabriolet Audi Q7 (model year 2009), Audi Q5, Audi R8 (model year 2009), Audi TT Coupé / TT Roadster (model year 2009)
<b>BMW:</b>	from august 2007: BMW 3 Series, BMW 5 Series, BMW 6 Series, BMW 7 Series, BMW X3, BMW X5 - BMW X6
<b>Jaguar:</b>	XF
<b>Land Rover:</b>	Range Rover
<b>Lexus:</b>	IS, GS, RX, LS
<b>Maserati:</b>	Coupé, Granturismo, Quattroporte
<b>Mercedes-Benz:</b>	from model year 2007: S-Class, SL-Class, CL-Class, CLS-Class, SLK-Class, E-Class, G-Class - from 01/2008: M-Class, GL-Class, R-Class
<b>MINI:</b>	MINI Cooper S, MINI One, MINI Cooper, MINI Cooper D, MINI Cooper Clubman, MINI Cooper S Clubman , MINI Cooper
<b>Porsche:</b>	911 Carrera, 911 Targa, 911 Turbo, Boxster, Cayman - from 22/2008: Cayenne
<b>Toyota:</b>	Auris, Corolla, Avensis, RAV4, Land Cruiser
<b>Volkswagen:</b>	Eos, Jetta, Golf, Golf Plus, New Beetle, Passat - from 22/2008: Phaeton, Touareg
<b>Volvo:</b>	XC90, S80, C70, V70, XC60, V50, S40, C30

UK	Company	Frequency	Mod.	Transmitter Type	Notes
<b>H</b>					
631	Holder	40 Mhz	FSK	TX04-40-15	
632		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
633	Homentry	433 Mhz	ASK	HE4331	
634	Huth	40 Mhz	FSK	T102497-40-5	
635		40 Mhz	FSK	T397-40-2	
636		868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7
637	HUTYRA	868 Mhz	FSK	TX03-868-4	ab/up/depuis/dal/desde Software Version 7